

---

Subject: Re: Save some trouble....(unabashed plug)  
Posted by [Wayne Parham](#) on Fri, 06 May 2005 20:26:01 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Agreed about cone breakup behavior. That's one of the main concerns when building a DI matched two-way because the crossover point is rather high. As for E-Mail addresses, I do have them and intended to include them in my last post. But I've noticed they've taken down employee direct E-Mail links from the Eminence website, so out of respect for their privacy, I didn't include them. Maybe they were having problems with SPAM or something. They're very easy to contact though, just give 'em a call and ask for them by name.

---