Subject: Need to get some work done.
Posted by Leland Crooks on Tue, 25 Oct 2005 12:28:40 GMT
View Forum Message <> Reply to Message

About all I've done the last day or two is think about this. Gotta get some real work for profit done. BUT, I had another thought.I'm going to taper the end of the inlet. Venturi shape like in a jet well pump. It should increase the velocity of the airflow on the return stroke of the diaphragm. Might even cause a low pressure zone at the outlets, increasing movement even more.