

---

Subject: Re: 2500 hz hump

Posted by [Wayne Parham](#) on Wed, 14 Dec 2005 20:10:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

There are lots of things manufacturers have done to reduce the problems surrounding breakup modes, mostly by working with different materials and cone geometries.

---