

---

Subject: Re: How to measure capacitance?

Posted by [Bill Epstein](#) on Mon, 26 May 2008 11:14:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I get a reading of .093nF very briefly, then back to zero, over the 9' of the cables but that can't be right. What's the right way to measure?

---