
Subject: Re: Corner horns without the triangular baffle
Posted by [Wayne Parham](#) on Sun, 14 May 2006 17:57:34 GMT
[View Forum Message](#) <> [Reply to Message](#)

Could be that the top and bottom sections vibrated a little bit like a diving board until you added the rear panels. The design is strong and rigid when all the panels are used, but if the back is omitted, it may leave the unbraced top and bottom sections free to vibrate.
