
Subject: Re: I'm working on that boxiness
Posted by [Bill Epstein](#) on Sun, 13 Aug 2006 12:15:22 GMT
[View Forum Message](#) <> [Reply to Message](#)

Kind of a 'hollow' sound. I took apart the third order BW and left it crossed at 3000 with just the 13.25 cap first order. Then swapped out the 1 mH coil replaced it with .5 on the woofer. Textbook. We'll see if that helps.
