

---

Subject: Re: Larger Driver

Posted by [Wayne Parham](#) on Mon, 04 Sep 2006 16:02:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm not aware of that problem and I've done some pretty intense tests of Eminence drivers. Like most other speakers, the leads from terminals to cone are looped to allow for excursion. What driver have you encountered this kind of failure from?

---