

---

Subject: Re: Light bulbs

Posted by [GarMan](#) on Mon, 18 Sep 2006 13:40:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Paul, The lamp is not located ahead of the entire crossover network. Just ahead of the HP filter. The lamp should not be in the woofer's signal path.

---