

---

Subject: Re: Pioneer RT - 909

Posted by [Wayne Parham](#) on Sat, 20 Dec 2008 17:48:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have an RT-909, and haven't had that problem. The usual problem with 909's is slow speed or uneven speed, often the result of the pinch roller wearing out. You might do a search of the Tape forum here. There have been several discussions about the Pioneer RT 909.

Tape forum

---