

---

Subject: Re: Pro 4

Posted by [Wayne Parham](#) on Fri, 21 Dec 2007 22:58:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The driver and horn displace 120 cubic inches. Cabinet tuning is fairly immune to small changes, so you'll be OK. To get a feel for how much a change will affect response, modify port size or some other parameter in one of the box modeling programs and see how much effect there is.

---