

---

Subject: 12Pi v2

Posted by [Roland Gama](#) on Mon, 18 Feb 2008 13:10:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello Wayne, There seems to be an error with the external panels measurement. The plans show that the 45 degree cut on the external panels begin at  $38-7/32$  from the edge of the mouth opening while all other panel cuts makes this one to be  $36-3/8$  (ie a difference of about 2 inches.) for things to click in place. Am I right? Roland.

---