

---

Subject: Re: Speaker setup

Posted by [Wayne Parham](#) on Thu, 09 Apr 2009 15:28:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Actually, the cabinet volume is fine for the 2226, it's the Helmholtz frequency that's wrong. The

port was right for the woofer chosen. So you would need to change the port if you changed the woofer. The problem is it's hard to resize a woofer hole and/or port and do a good job. You're limited on the tools you can use. So I understand your dilemma. Sorry, but I know of know

looking at AE Speakers, to see if they have a woofer or can make one for this application. On first glance, the TD-12S specs look right.

---