

---

Subject: Re: new 4 Pis near completion finally  
Posted by [Wayne Parham](#) on Tue, 21 Jul 2009 17:29:55 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

No problem at all with the insulation near the port. It's normal for the sheet on the back to be about an inch or inch and a half away from the internal opening of the port.

---