

---

Subject: Re: Marshall AVT100 Problems

Posted by [Wayne Parham](#) on Mon, 17 Aug 2009 13:51:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds to me like it might be a cold solder joint or mechanical connection. I would re-heat every solder joint and flow in a small amount of new solder. I would also reseal every mechanical connection and socketed component by removing and reinserting them. Start with that, it may fix the problem.

---