
Subject: Re: Don't forget to check under the hood
Posted by [Bill Epstein](#) on Wed, 25 Nov 2009 21:30:59 GMT
[View Forum Message](#) <> [Reply to Message](#)

I recall the B&C terminals being better but maybe I have them confused with Altecs. Now those are stout terminals!

Your post encourages me to do the job tomorrow AM with heatsinks on those 'tinsel' wires to the driver and have a look at the B&Cs as well.
