

---

Subject: Pioneer RT-909

Posted by [timestar](#) on Fri, 08 Jan 2010 19:25:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a RT-909 with a 7.5 speed problem - way too slow...3.75 is fine, but 7.5 almost runs the same as 3.75. Help anyone?

---