
Subject: Re: Pioneer RT-909

Posted by [timestar](#) on Fri, 08 Jan 2010 19:59:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

Thanks, Wayne. I'll check the pinch rollers, but I think they are new. What kind of adjustment did yours need? I'm told by local repair that it is probably a problem on the DC board at a cost of \$250.

Robert
