

---

Subject: Re: Pioneer RT-909

Posted by [AudioAJ](#) on Thu, 18 Feb 2010 19:27:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

timestar wrote on Fri, 08 January 2010 15:01 It was the belt...I just put a new one on.

For me, whenever I've had problems with speed issues, that's usually the first place I check. Go with the easiest and cheapest fixes first.

---