

---

Subject: philco model 111

Posted by [capbuster](#) on Tue, 13 Apr 2010 01:19:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a philco model 111 .Recapped all new resistors ,all good tubes , antenna coils check good . After about 15 minutes loses reception. Turn off let cool does it again. Ran a long wire antenna picks up stations . What would make this happen ? Acts like something gets hot quits working. I watched tubes no filaments cutting out. DO NOT KNOW WHAT TO CHECK .

Thanks Capbuster.

---