

---

Subject: Re: philco model 111

Posted by [Wayne Parham](#) on Tue, 13 Apr 2010 01:41:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Swap all the capacitors with polypropylene caps, and I'll bet that fixes it. Old radios actually are more likely to have bad caps even than tubes.

---