Subject: philco 48-1253

Posted by capbuster on Sun, 02 May 2010 23:19:01 GMT

View Forum Message <> Reply to Message

I have this set . It has that hum . Would it be okay just to change the electrolytic caps, and line caps leave the rest alone .

Works great just has that hum.

THANKS.CAPBUSTER