

---

Subject: Re: zenith transoceanic b600, 6A40 chassis removal  
Posted by [Wayne Parham](#) on Tue, 18 May 2010 04:29:25 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Personally, I'd replace all the electrolytic caps with polypropelene caps. I think it's safe to assume they're weak beyond usability. Don't replace resistors unless you know they're bad (which I doubt). Selenium rectifiers are high failure items, although most radios I have with them, they're fine.

---