

---

Subject: Re: Edison type 7R

Posted by [ilikemac83](#) on Tue, 22 Jun 2010 02:42:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Amazingly no tubes were missing when I got it, but I did replace 2 227's that read weak. And after replacing a very bad power cord and slowly bringing up the voltage I do get (and only get) a 60hz hum. So all that's left to do now is take a hammer to it or something so I can get to the capacitors inside the metal boxes. They are held on by what looks like non-removable pins since they probably thought nothing bad would ever happen to them old capacitors COUGH COUGH yeah riiight!

---