

---

Subject: Re: Edison type 7R

Posted by [Wayne Parham](#) on Wed, 23 Jun 2010 03:06:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

That is so, so cool! Love the cotton insulated wire. Chassis looks like it's in pretty good shape, just needs a little cleaning.

The 60Hz hum symptom is a pretty common one. It can mean just about anything. Could be as simple as coupling caps gone bad, and if they haven't been replaced, that's likely. I generally replace all paper/oil caps with polys, first thing. Could be a tube too, or alignment, but I'd start with the caps.

Do you have a tube tester? An oscilloscope?

---