

---

Subject: Re: Airline 62-2704 Need Help

Posted by [Wayne Parham](#) on Thu, 01 Jul 2010 00:02:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You might be right about the antenna - I was going by what you said, the fact that there were three wires. I assumed you saw them as inputs to the RF input tube, through their own trimmer caps. Trace those wires back, maybe they're not antenna leads at all.

About the schematic search, I'd look for a match on the chassis and tube complement. When you have a visual match, you have the right schematics.

There are no new field coil speakers, at least not the kind for table radios. There are a few for hifi, but they're very expensive, not anything like what you'd put in a radio like this. The only way to find a field coil speaker is as a pull, a used part from something else. You can probably find one on eBay.