

---

Subject: Re: Airline 62-2704 Need Help

Posted by [Wayne Parham](#) on Sat, 10 Jul 2010 13:09:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Let us know when it arrives. Be sure to identify the field coil and voice coil windings, and measure them to make sure neither one is open.

---