

---

Subject: Re: philco 48-1253

Posted by [capbuster](#) on Sat, 14 Aug 2010 16:32:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

My concern is it is a original can cap. It has two leads on bottom neg. & pos. The neg goes into can positive lead just there going to nothing. Soldered to lead on bottom of can but nothing else there.

Thanks Capbuster.

---