
Subject: Re: Zenith Transoceanic G500 restoration
Posted by [Wayne Parham](#) on Sun, 22 Aug 2010 16:42:38 GMT
[View Forum Message](#) <> [Reply to Message](#)

That's awesome! I have a couple Transoceanics and they're very good radios.

Yes, that part you have is a resistor. Is it bad? I'd probably measure across it to see, and only replace it if it's bad. I tend to swap caps blindly on old radios like that, because they're almost always bad. But wirewound resistors like that don't go bad with age.