

---

Subject: Re: Christmas Wishlist

Posted by [Adveser](#) on Wed, 15 Dec 2010 01:08:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I don't think it is the wiring Fred, It doesn't have that classic 100% OOP sound. I think the signals are summing improperly causing the phase issue. I chalk it up to comparators having different output values or the tolerances not playing well together.

I'm not all that worried about it considering I don't plan on using the HP jack, but it does raise a red flag on the quality of the other components.

---