

---

Subject: Re: [Pi2 Tower] Insulation on braces

Posted by [Wayne Parham](#) on Mon, 03 Jan 2011 13:41:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The insulation on the braces should span the cross-section left to right and front to back, sort of like making "compartments" inside the speaker. The sound has to pass through the insulation to get to the port. It blocks midrange but bass passes right through. Like this:

---