

---

Subject: Re: [Pi2 Tower] Insulation on braces

Posted by [Wayne Parham](#) on Thu, 06 Jan 2011 15:55:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You're right, only two sets of braces are required, one 1/3rd the way from the top (just under the midwoofer) and the other 1/3rd the way up from the bottom. They should have insulation sitting on them, spanning the cross-section.

That photo was one of Shane's builds, and he put in an extra brace. That's OK, but not required. The reason I posted this photo was to show how the insulation sitting on top of the braces spans the cross-section of the cabinet.

---