

---

Subject: Re: Pro-Ject Debut III Noise with Speed Box  
Posted by [Wayne Parham](#) on Tue, 03 May 2011 23:49:45 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

My guess is the motor was bad from the get-go. Shouldn't have any problems with just 200 hours on it. Turntables don't put any unusual loads on the motor, not much load of any sort.

---