
Subject: Dynavector 10X5 Assist

Posted by [gofar99](#) on Mon, 01 Aug 2011 22:44:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi Everyone, My favorite TT wasn't sound quite right so I went through all the checks and ultimately it pointed to the cartridge. When I looked at it under magnification (see photo) the cantilever is warped to one side. Not bent or kinked, just bowed. Anyone ever see this before? Also anyone know a good place to get it fixed?

File Attachments

1) [Image7.jpg](#), downloaded 4042 times
