

---

Subject: Re: crossover board assembly

Posted by [Wayne Parham](#) on Mon, 29 Aug 2011 23:02:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

No trick to it at all. Just trim the component leads to fit and solder them on. The photo below shows me drawing an outline on some gasket material, and it also shows a crossover in enough detail for you to see what I mean:

---