

---

Subject: Re: JBL 2226H question: is this right?

Posted by [haanjamin](#) on Sat, 24 Dec 2011 17:38:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Did some more free air testing and both woofers start distorting at 23 volts at all frequencies I tested from 20-200HZ. So I have about 1/10th the power handling as I should have. Since they distort at the same power input, would that be a sign of a knockoff recone job? I can't tell if the wire coming through the cone is flat or circular cross section because of too much black glue covering it.

One of them also has a rattle that starts at 6 volts that seems to go away when I block the cooling ports.

Recones should be able to fix all this, correct?

---