

---

Subject: Re: Anyone have info on these?

Posted by [gofar99](#) on Sat, 11 Aug 2012 15:37:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Clearly from Utah as there are similar ones on ebay. Still no clue on what the "factory" parameters were. Nor any ideas on how to get them to match. I have considered that they may need to be broken in after sitting for years. Perhaps just feeding in a signal near the resonance points for a few days at low level. Ideas are always welcome.

---