Subject: Re: 4Pi measurements Posted by Wayne Parham on Sun, 04 Nov 2012 01:50:08 GMT View Forum Message <> Reply to Message

zheka wrote on Sat, 03 November 2012 15:26I finally had a chance to open the speaker with unhealthy boost in the crossover region - the zobel was disconnected! what a relief. I thought that was probably the cause. Glad you took the time to measure the speakers - It sure helped you nail it down!

Page 1 of 1 ---- Generated from AudioRoundTable.com