

---

Subject: Re: 4Pi crossover study

Posted by [Wayne Parham](#) on Sat, 27 Jul 2013 15:01:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, that looks good. The other driver must be messed up.

Can you send it back for a warranty replacement? If not, you might want to take it apart and see if there is debris in the phase plug. Make sure it is clear and free of dust. Sometimes just taking it apart and putting it back together recenters the voice coil and fixes problems like these too.

---