Subject: Re: 4Pi crossover study Posted by Wayne Parham on Sat, 27 Jul 2013 15:01:38 GMT

View Forum Message <> Reply to Message

Yes, that looks good. The other driver must be messed up.

Can you send it back for a warranty replacement? If not, you might want to take it apart and see if there is debris in the phase plug. Make sure it is clear and free of dust. Sometimes just taking it apart and putting it back together recenters the voice coil and fixes problems like these too.