

---

Subject: vinagery/acic smell.....

Posted by [ARTIdaho](#) on Sun, 06 Nov 2005 23:22:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

after running tuner? Int. amp for awhile. Don't see any leakage from components.....is this electrolyte from a capacitor?? Thanx much, Chuck

---