

---

Subject: Problem with Sansui 6060 receiver

Posted by [Ross Rakoff](#) on Thu, 05 Jul 2007 17:57:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a sansui 6060 receiver that sounds great and everything about it works, but the left side has the sound that sounds like embers burniong of the tip of a camp fire. This sound is present when volume is turned all the way down, on all input stages and when listed to on head phones. Does anyone know how to fix this problem?-Ross

---