
Subject: Re: Problem with Sansui 6060 receiver
Posted by [Wayne Parham](#) on Fri, 06 Jul 2007 02:56:19 GMT
[View Forum Message](#) <> [Reply to Message](#)

Perhaps it has a bad solder or possibly a bad resistor or transistor. You would think that a bad transistor would simply give a dead channel, but I've had 'em go bad like that. To me, when it happens, it sounds like there's arcing inside the substrate.
