

---

Subject: Re: Problem with Sansui 6060 receiver  
Posted by [DAISYMAE](#) on Tue, 24 Jul 2007 11:23:08 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

I have a 6060 on the bench right now with the same problem. The problem was found to be the 2SC727 transistors in the driver Board. I replaced them with MPS A18 transistors and all is fine now. Frequently in 50 year old equipment transistors become noisy.

---