

---

Subject: Sansui AU-6500

Posted by [Ross Rakoff](#) on Sat, 22 Mar 2008 22:24:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a Sansui AU-6500 Integrated and when I got it it worked fine except for the dirty pots. I lubed it up and after that the right side of the phono section puts out a loud hum. The left side is fine. Is any one familiar enough with the amp to tell me where the part is that needs to be replaced is and how to replace it. I assume that I misfired the contact solution somewhere I should have.-Ross

---