

---

Subject: Re: 7Pi Build 2014

Posted by [rkeman](#) on Fri, 12 Sep 2014 20:02:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Check everything! Crossovers, wiring, insulation, drivers, driver gaskets, back panel bracing, amplifier... If both speakers have the problem it is probably a crossover or construction issue because simultaneously defective drivers or channels of amplification are very unlikely. The build is fairly complicated and it is very easy to miss something. When assembling a 3PI, the insulation in one speaker came loose and fell against the back of the woofer cone and it sounded very bad indeed!

---