
Subject: Re: 7Pi Build 2014

Posted by [compaddict](#) on Fri, 12 Sep 2014 22:11:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

Not the problem, but one resister was rattling around in the XO box. Nothing close to touching it. A mystery. I soldered it back on and they still sound bad.

Picture of XO and wiring. Wires with black shrink wrap are negative all the way back to the drivers.

File Attachments

1) [7pi XO.jpg](#), downloaded 9728 times
