

---

Subject: Re: 7Pi Build 2014

Posted by [compaddict](#) on Sun, 14 Sep 2014 16:15:58 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

First thing, it seems that 2226h are wired "black to + forces positive displacement". Good to know. I will fix that in the XO box as well as the other suggestions.

The resistor came off by itself inside the XO box. It's a mystery because nothing could have knocked it off.

How much clearance is optimal between the mid cone and the panel it's mounted to?

Mid horn bracing is not an issue.. The back panel seal is not perfect now but I will fix that once I determine the proper clearance for the mid driver.

---