

---

Subject: Re: 7Pi Build 2014

Posted by [Wayne Parham](#) on Mon, 15 Sep 2014 13:10:45 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

It's a zero-clearance fit. The gasket and the plate must fit snug. It's just that the cone cannot rub against anything. All panels must be braced too.

---