

---

Subject: Re: 7Pi Build 2014

Posted by [Wayne Parham](#) on Mon, 15 Sep 2014 21:23:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

heard, due in part to the horn loading and part due to its close proximity to the corner apex, which prevents self-interference. So whatever is going wrong must be severe.

---