

---

Subject: Re: 7Pi Build 2014

Posted by [Wayne Parham](#) on Mon, 06 Oct 2014 19:00:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Again, we see that there is a huge rolloff up high. It looks like the compression driver tweeter isn't even connected. That's where we need to focus, I think. Concentrate on what may be causing the lack of HF output, whether it be bad crossover, wiring or compression driver.

---